

Service Technical Information

MODEL NO.	NSX-A115 / S111 / S112 / S116 / S119 / S16
SUBJECT	Notes on replacing μ -COM

REF.No. :G - A0 - 063- E0

DATE :19. SEP. 2000

<CONTENTS>

Two types of CD mechanisms exist, and the respective front P.W.B boards have a different μ -COM.

The μ -COM on the boards are not compatible with each other.
Be sure to confirm the type of CD mechanism mounted, and replace the μ -COM according to the table below:

CD mechanism

1. 4ZG-1S3 / S4 (IC, CXA1992 / CXD2589 mounted)
2. 4ZG-1Z3 / Z4 (IC, LA9241 / LC78622 mounted)

* A service manual concerning this matter will be issued in September.

<NOTE>

Refer to G-99-023 if the code of a μ -COM ends with characters/numbers different from those of the codes in the table below.

Ref.	Parts Code	Description	Remarks
IC101	8Z-NFA-661-010	C-IC,M38B59MFHP-113FP	4ZG-1S3 / S4
IC101	8Z-NFA-671-010	C-IC,M38B59MFHP-117FP	4ZG-1Z3 / Z4

G	R	Code No.	Access Code	Modified Ser. No.	Parts Schedule
-	-	-	-	S****09***** ~	-